

General Environmental Incident Summary

Incident: 4020 **Date/Time Notice:** 2/14/2016 **DEM Incident No:**

Responsible Party: Dynamic Well Services Inc.

Date Incident: 2/6/2016 **Time Incident:** **Duration:**

County: Williams **Twp:** 154 **Rng:** 101 **Sec:** 10 **Qtr:**

Lat: 48.17860 **Long:** -103.65760 **Method:** Interpolation from map

Location Description: Residential area drive way, address is 3805 25th ct Williston ND.

Submitted By: Jeff Vigil

Affiliation:

Address: 4957 148th Ave NW

City: Williston

State: ND

Zip: 58801

Received By:

Contact Person:

4957 148th Ave NW
Williston, ND 58801

Distance Nearest Occupied Building:

Release Contained: Yes

Type of Incident: Leak UNK

Description of Released Contaminant: Diesel

Volume Spilled:

Ag Related: No

EPA Extremely Hazardous Substance: Unknown

Reported to NRC: Unknown

Cause of Incident:

Not sure what caused the diesel leak onto the ground or how long it was leaking for.

Risk Evaluation:

Health Hazards, and Irritant

of Fatalities:

of Injuries:

Affected Medium: 04 - water and soil

Potential Environmental Impacts:

contaminated storm water, soils

Action Taken or Planned:

Contacted Garner Environmental services for Containment and clean up.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 2/14/2016 **Status:** Inspection

Author: Kangas, Kathleen

Updated Volume:

Notes:

NDDoH representatives on site at 2 p.m. 02.10.16. Weather was 30 degrees F, cloudy, wind 9 mph NNW. Garner Emergency Response was on site doing cleanup. Apparent diesel tank leak that ran down the street many blocks in a residential area and impacted storm drains. While the submitted report does not state an amount, personnel on site relayed an approximate released amount of 100-150 gallons of diesel fuel. There is staining along a cul-de-sac and impact in the front yard of a residence. On-site personnel relayed that the smell of diesel was noted around several drainage/manhole cover areas many blocks from the site. This release was not contained. NDDoH representatives took water samples at the apparent stormwater outlet area off of Bison Drive. Garner Emergency Response personnel continued to spray hot water and Petro-clean on affected areas, using a vac truck to suck up contamination. Garner indicated they had sampled the impacted soil in the residential yard and will await results before backfilling. Sample results will be relayed to the NDDoH.

Date: 2/19/2016 **Status:** Inspection

Author: Stockdill, Scott

Updated Volume:

Notes:

Arrived on location 9:00 AM on 2/17/2016.

Met with third party contractor, Williams County Emergency Management, and responsible party.

Majority of site has been cleaned up with no smell of diesel present at the point of impact. The contractor has opened up the impacted storm drains and sucked out 130 barrels of contaminated water. Absorbent booms have been placed in the drains to further collect stray hydrocarbons. When cleanup is complete, a report will be sent to the NDDoH.

This spill has been turned over to the Division of Water Quality Permits Program, since it has impacted city storm sewers. The Spill Response Program will retain oversight on the surficial area that has been impacted.

More follow-up is necessary when the snow has melted to ensure proper cleanup.